EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	19410	fuse ((low$2 adj melting adj point) or tin)	US-PGPUB; USPAT; USOCR	AND	ON	2008/01/22 13:54
L2	0	(fuse near2 bridge) (bridge near4 ((low$2 adj melting adj point) or tin)) (fuse near2 strip)	US-PGPUB; USPAT; USOCR	AND	ON	2008/01/22 13:56
L3	12	(fuse near2 bridge) (bridge near4 ((low$2 adj melting adj point) or tin))	US-PGPUB; USPAT; USOCR	AND	ON	2008/01/22 13:56